

2019 Toyota Tacoma 4x4 Double Cab V6 Manual TRD Sport

VIN # 5TFCZ5AN0KX180696

16208 MILES	Crew Pickup	3.5 liters 3.5 L Regular Unleaded V-6	Four Wheel Drive MANUAL
----------------	-------------	--	----------------------------

INSPECTION LOCATION:  
4327 EASTERN AVE, CINCINNATI, OH 45226, USA

EXT: Magnetic Grey Metallic INT: Dark Grey

INSPECTION DATE:  
NOVEMBER 21, 2020 @ 15:50



BODY:



GLASS:



PART:



TIRES:



WHEELS:



DISCLOSURES:



Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Interior (0)





No damage

Exterior (15)

LEFT SIDE





Info Info Severe

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
Left Side Front Door		Has Minor Dent	< 2 inch - No Paint Damage	Report only
Left Side Rear Wheel		Has Medium Curbing	5 inch to 6 inch	Refinish
Left Side Lower Bedside		Has Minor Dent	< 2 inch - No Paint Damage	Report only

 <b>Left Side Lower Bedside</b>		Has Minor Scratch	< 2 inch - No Paint Damage	Report only
 <b>Left Side Front Tire</b>		Is Medium Worn	Medium Signs of Wear	Replace
 <b>Left Side Rear Tire</b>		Is Medium Worn	Medium Signs of Wear	Replace





RIGHT SIDE

Info     **Severe**

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
 <b>Right Side Front Tire</b>		Is Medium Worn	Medium Signs of Wear	Replace
 <b>Right Side Rear Tire</b>		Is Medium Worn	Medium Signs of Wear	Replace
 <b>Right Side Lower Bedside</b>		Has Minor Scratch	2 inch to 4 inch Has Paint Damage	Refinish









FRONT SIDE

Info     **Severe**

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
 <b>Front Bumper</b>		Has Minor Scratch	< 2 inch - Has Paint Damage	Report only
 <b>Front Bumper</b>		Has Minor Scratch	< 2 inch - Has Paint Damage	Report only

REAR SIDE






Info     **Severe**

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
 <b>Left Taillight</b>		Is Broken	Body Panel Not Aligned / Cracked / Not in Proper Place	Replace
 <b>Rear Bumper</b>		Has Minor Dent	< 2 inch - No Paint Damage	Report only
 <b>Rear Bumper</b>		Has Minor Dent	< 2 inch - No Paint Damage	Report only
 <b>Rear Tailgate</b>		Has Minor Scratch	< 2 inch - Has Paint Damage	Report only

WINDSHIELD

No damage

Tires & Wheels

-  Like New
-  Good Condition
-  Medium Worn
-  Major Worn
-  Snow Tire

**LEFT FRONT**

Is Medium Worn

Medium Signs of Wear

5/32, 4/32

None

**RIGHT FRONT**

Is Medium Worn

Medium Signs of Wear

5/32, 4/32

None

**LEFT REAR**

Is Medium Worn

Medium Signs of Wear

5/32, 4/32

None


**RIGHT REAR**

Is Medium Worn

Medium Signs of Wear

5/32, 4/32

None



**Announcements**

TITLE PRESENT	No
ALL KEYS PRESENT	1

**Disclosures**

TITLE ORIGIN	
INCORRECT VEHICLE MARKING	No
TITLE BRANDED	None
CROSS BORDER	No
VIN PLATE ISSUES	No
WARRANTY CANCELLED	No
STOLEN AND RECOVERED	No

ODOMETER	
ODOM 5 DIGIT	No
ODOM FAULTY	No
ODOM IN OTHER	No
ODOM REPLACED	No

ODOM ROLL BACK	No
ODOM UNREADABLE	No
TMU	No
RMU	16208, 2020-11-21

DAMAGE	
ADJACENT PANELS REPLACED	No
EXCESSIVE RUST	No
FIRE DAMAGE	No
FLOOD DAMAGE	No
IRREPARABLE	No
STRUCTURAL DAMAGE	No

MECHANICAL	
ABS DEFECTIVE	No
AIR BAG DEFECTIVE	No
ALTERNATE FUEL	No
NONE SPECS	No

PREVIOUS USER	
PREVIOUS DAILY RENTAL	No
PREVIOUS DRIVING SCHOOL VEHICLE	No
PREVIOUS EMERGENCY VEHICLE	No
PREVIOUS POLICE VEHICLE	No
PREVIOUS TAXI LIMO	No