

English Français

2013 Ford Galaxy 2.0 TDCi 138 BHP Titanium A Galaxy 2.0 TDCi 138 BHP Titanium A VIN # **132D13878**

290303 KILOMETRES	MPV	- -	- AUTOMATIC
----------------------	-----	--------	----------------

INSPECTION LOCATION:

EXT: GREY

INT: -

INSPECTION DATE:
AUGUST 15, 2022 @ 10:46

BODY:



GLASS:



PART:



DISCLOSURES:



Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Interior (1)

Info ● ● ● ● Severe

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
● Interior		The seats or carpets have stains	Stained	Refinish

Exterior (19)

LEFT SIDE

Info ● ● ● ● Severe

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
● Left Rocker Panel		Has Multiple Major Scratches - Not Through Paint	10 or more scratches	Repair & Refinish

● Front Left
Fender

Has Minor Scratches - Not Through Paint

1/8 to 1/2 inch - NAAA
Acceptable

Repair & Refinish

RIGHT SIDE

Info ● ● ● ● Severe

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
● Front Right Door	—————	Has Major Dent - Not Through Paint	9 inches to 10 inches	Replace
● Right Rocker Panel	—————	Has Multiple Minor Scratches - Not Through Paint	2	Refinish
● Front Right Door	—————	Has Medium Dent - Not Through Paint	5 to 6 inches	Repair & Refinish
● Rear Right Door	—————	Has Major Scratches - Not Through Paint	9 inches to 10 inches	Repair & Refinish
● Right Quarter Panel	—————	Has Multiple Minor Scratches - Not Through Paint	2	Refinish
● Rear Right Door	—————	Has Minor Dent - Not Through Paint	1/8 to 1 inch - NAAA Acceptable	PDR Repair
● Rear Right Door	—————	Has Medium Dent - Not Through Paint	5 to 6 inches	Repair & Refinish

FRONT SIDE



Info ● ● ● ● Severe

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
● Front Bumper Cover	—————	Has Multiple Minor Scratches - Not Through Paint	2	Refinish
● Front Bumper Cover	—————	Has Minor Dent - Not Through Paint	1/8 to 1 inch - NAAA Acceptable	PDR Repair

REAR SIDE

Info ● ● ● ● Severe

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
● Trailer Hitch	—————	Has Major Rust	> 6 inches	Replace
● Rear Bumper Cover	—————	Has Minor Scratches - Not Through Paint	1/8 to 1/2 inch - NAAA Acceptable	Repair & Refinish
● Rear Bumper Cover	—————	Has Medium Scrape	5 to 6 inches	Repair & Refinish
● Rear Bumper Cover	—————	Has Minor Scratches - Not Through Paint	1/8 to 1/2 inch - NAAA Acceptable	Repair & Refinish
● Rear Bumper Cover	—————	Has Multiple Minor Scratches - Not Through Paint	2	Refinish
● Rear Bumper Cover	—————	Has Small Crack	1/8 to 1/2 inch - NAAA Acceptable	Replace

 Rear Hatch	—————	Has Minor Dent - Not Through Paint	1/8 to 1 inch - NAAA Acceptable	PDR Repair
 Rear Bumper Cover	—————	Has Minor Dent - Not Through Paint	1/8 to 1 inch - NAAA Acceptable	Repair & Refinish

WINDSHIELD

No damage